



WW SURFACE RESOURCES PLAN

Reference

- Plants (Resource)
- Pump Station

- Indicated resources
- Inferred resources
- Env. Clean-up (Inventory & Depleted)
- Shaft Areas
- Tailings Pipelines
- Railways
- Mine Boundary

Typical Chamber of Mines Dump Code:
 L donates slime and A sand 2226DCL/8
 Dump number 2226DCF/8

